

RC No. 01/SSC /SA/2025

Office of the Deputy Executive Engineer  
PRI Sub Division, Naidupeta, Dt 15.04.2025

From  
Sri G. Suresh Babu B.Tech,  
Deputy Executive Engineer,  
PRI Sub Division Naidupeta.

To  
The Principal,  
TINYTOTS E.M High School,  
Sullurupeta.


Sir,

**Sub:** Soundness Certificate – PRI Sub Division Naidupeta – Representation of the Principal TINYTOTS E.M High School. Survey No:128/2 & 128/3. Sullurupeta in Tirupati District – Issue of School Building Structural Soundness Certificate - Regarding.

**Ref:** Letter Dated: 02.04.2025 of the Principal, TINYTOTS E.M High School, Sullurupeta.

\*\*\*\*\*


As per reference cited above the Deputy Executive Engineer, PRI Sub Division, Naidupeta has inspected the above school building on 07.04.2025 and submitted Soundness Certificate to TINYTOTS E.M High School, Survey No:128/2 & 128/3, on 15.04.2025.



Encl: Soundness Certificate

Yours Faithfully,

  
Deputy Executive Engineer,  
PRI Sub Division, Naidupeta

  
15-4-2025

## SOUNDNESS CERTIFICATE


I have inspected the TINYTOTS E.M High School building premises along with concerned M.E.O, the building is RCC structure of 3 floors with the floors plinth area details as follows as per approved plan.

S.NO	Floors	Plan 1 Building	Plan 2 Building
1	Ground Floor	352.46 Sqmt	352.46 Sqmt
2	First Floor	352.46 Sqmt	352.46 Sqmt
3	Second Floor	352.46 Sqmt	352.46 Sqmt
	Total	1057.38 Sqmt	1057.38 Sqmt

The School is functioning in own building with Survey No:128/2 & 128/3. Sullurupeta in Tirupati District.

The Structure is sound enough to conduct the classes as on date.

  
Deputy Executive Engineer,  
PRI Sub Division Naidupeta

  
15-4-2025

  
Assistant Executive Engineer  
MPP Sullurupeta

